

# 25 POINT SPA CHECK UP

NOW THAT YOUR WARRANTY IS READY TO EXPIRE, IT'S TIME TO GET YOUR SPA TUNED!



### What will we do during our visit?


- Our Factory Trained Service Technicians will perform a detailed check on your spa (see back for details)
- We will replace the parts covered under the 5 year warranty
- We will test items that were covered by your 2 year warranty, one year warranty, and those covered only at the time of delivery
- Most of the parts that need to be replaced can be done during the check up, however some parts may need to be ordered or picked up at our warehouse
- The price on the parts that need to be replaced are specially priced out for installation during the check up
- Any parts that need to be ordered or are in our warehouse, will also be specially priced for you

## SPA CHECK UP COST: \$129.99

Please include a phone number for our technician to call in order to get permission to replace parts that are no longer in warranty.

We want to keep your spa running just like new so that you can have many more relaxing years to come!

Schedule your Spa Check Up By Calling: 800-649-5952 ext. 25





# 25 Point Spa Check List

ITEMS LISTED BELOW ARE WHAT WE WILL CHECK DURING THE 25 POINT SPA CHECK UP

#### **FIVE YEAR WARRANTY PARTS**

- Surface of the spa
- Jet pump
- Auxiliary Control
- Jet Pump One
- Jet Pump Two (If applicable)
- Circulation Pump
- Heater
- IQ Panel
- Spa Leaks
- Moto Massage Jets
- Air Levers
- Jet Bezels
- GFCI Test Button
- Cabinet Boards

#### TWO YEAR WARRANTY PARTS

- LED Lights Under Water
- LED Lights on Bar Top
- Cover Water Logged

#### **ONE YEAR WARRANTY PARTS**

- Fresh Water Ozone\*
- Fresh Water Ozone Check Valve\*
- Remote Control Battery
- ACE Cell

#### ITEMS NOT COVERED UNDER WARRANTY

- Tears in the Cover
- Cover Clip
- Filter Condition
- Filter Stand Pipe

The Fresh Water Ozonator lasts about 3-4 years. Although you may be seeing bubbles coming up from the Ozonator, it may not be working properly. Our technicians will test the output and will confirm if it is working properly. Regular Price to install a new one is \$595.00

SPECIAL PRICE DURING CHECK UP: \$399.00

The Ozone Check Valve also needs replacing about every 3-4 years. This valve prevents water in the spa to siphon out of the spa through the Ozonator during a power loss. We will automatically replace the Check Valve (\$14.40 value)

### SPA CHECK UP SPECIALS

- NEW \*SPA COVER 15% OFF!
  - HEATER REG. PRICE \$625

**SALE PRICE \$500** 

• IQ PANEL REG. PRICE \$825

**SALE PRICE \$675** 

MOTO MASSAGE REG. PRICE \$325

**SALE PRICE \$200** 

• DIVERTER VALVE REG. PRICE \$275

SALE PRICE \$156

\*Will need to be ordered